

CASTLEMANOR[®]

FREESTANDING & RETAINING WALL

DIMENSIONAL CHARACTER IN A MULTI-PIECE WALL SYSTEM



BELGARD
PAVES THE WAY[™]



BACKED BY
ANCHOR
DIAMOND[™]
INDUSTRY EXPERTS





CASTLEMANOR®

FREESTANDING & RETAINING WALL




DIMENSIONAL CHARACTER IN A MULTI-PIECE WALL SYSTEM


✔ FEATURES & BENEFITS


- Multi-piece wall system for increased installation flexibility
- Ideal for small freestanding walls, parapet walls, seat benches, pilasters, columns and outdoor living environments
- Build curved or straight, freestanding or retaining walls
- Each unit can be used as an exposed end unit or a 90° corner unit for less cuts
- No patterns required for random look
- Used for gravity walls up to 2.5 feet* at a near vertical batter or 3 feet* using the 9.5 degree batter/1 inch setback per unit option.
- Taller walls can be built using geosynthetic reinforcement when designed by a qualified engineer.
- Minimum outside radius of 5 feet
- Minimum inside radius of 3 feet

🧱 SHAPES & SIZES




CASTLEMANOR GRANA


-  6 x 6 / 4 x 10
-  6 x 12 / 10 x 10
-  6 x 16 / 14 x 10

 **CORNER**
3 x 10 x 12

 **CAP**
3 x 10 x 12

CASTLEMANOR RUSTIC

-  6 x 6 / 4 x 10
-  6 x 12 / 10 x 10
-  6 x 16 / 14 x 10

 **CORNER**
3 x 10 x 12

 **CAP**
3 x 10 x 12

 **UNIVERSAL PIN**
6" L x 3/8" D
Approx. 3.5 pins per sqft

🔥 AVAILABLE COLORS



TOSCANA



VICTORIAN



PROPOSITION 65 WARNING:

This product can expose you to chemicals including Crystalline Silica, which is known to the state of California to cause cancer, and Cadmium, which is known in the State of California to cause birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.



PROPOSICIÓN 65 ADVERTENCIA:

Este producto puede exponerle a productos químicos incluyendo sílica cristalino, que el estado de California para causar cáncer, y Cadmio, que en el estado de California se sabe que causa defectos de nacimiento u otros daños reproductivos. Para más información, vaya a P65Warnings.ca.gov.